





No. 9120RM
110 Volt AC

#	Description	Stock #	#	Description	Stock #
1.	Carriage Shaft	9150-15	21.	Cap Screw	9100-17
2.	Carriage	CARR-9	22.	Washer	9100-17A
3.	Wing Nut	SNK-3	23.	Buttonhead Screw	9100-18A
4.	Washer/Bearing Set	BBW-2	24.	Motor Bracket	9120-BRKT
5.	Top Jaw	TJAW-4	25.	Belt Guard Assembly	9120-14
6.	Spring	9100-13	26.	Buttonhead Screw	9150-21
7.	Bottom Jaw	BJAW-4	27.	Motor Pulley	9120-30
8.	Vise Stud	STUD-4	28.	Set Screw	9100-11
9.	Adjusting Gib Screw	9100-27	29.	Belt For 9120	9120-BELT
10.	Tracer	9120-13	30.	Motor Assembly	9120-MOTOR
11.	Washer	9100-26	31.	Cutter Nut	9150-29
12.	Cap Screw	9100-28	32.	Cutter Washers (2)	9100-6
13.	Bearings	9100-21	33.	Cutter	CW-23RM
14.	Set Screw	9100-11	34.	Gauge Shaft	9100-3
15.	Fiber Washer	9100-20	35.	Key Gauge	9150-14
16.	Machine Pulley	9100-19	36.	Tieover Bracket	9160-TIE
17.	Brush	TYX-3	37.	Nut	CM-50148
18.	Cutter Shaft	9160-3	38.	Screw	9100-17
19.	Brush Nut	9100-25	39.	Lock Washer	9100-17A
20.	Cutter Guard	9100-16	40.	Snap Ring	9100-21A



No. 9120RMDC
12 Volt DC

36



MINI SPEEDEX®
9120RM

No. 9120RMDC

<u>#</u>	<u>Description</u>	<u>Stock #</u>	<u>#</u>	<u>Description</u>	<u>Stock #</u>
1.	Carriage Shaft	9150-15	23.	Buttonhead Screw	9100-18A
2.	Carriage	CARR-9	24.	Motor Bracket	9120-BRKT
3.	Wing Nut	SNK-3	25.	Belt Guard Assembly	9120-14
4.	Washer/Bearing Set	BBW-2	26.	Buttonhead Screw	9150-21
5.	Top Jaw	TJAW-4	27.	Motor Pulley	9120-30
6.	Spring	9100-13	28.	Set Screw	9100-11
7.	Bottom Jaw	BJAW-4	29.	Belt For 9120	9120-BELT
8.	Vise Stud	STUD-4	30.	DC Motor	9120-DCMOTOR
9.	Adjusting Gib Screw	9100-27	31.	Cutter Nut	9150-29
10.	Tracer	9120-13	32.	Cutter Washers (2)	9100-6
11.	Washer	9100-26	33.	Cutter	CW-23RM
12.	Cap Screw	9100-28	34.	Gauge Shaft	9100-3
13.	Bearings	9100-21	35.	Key Gauge	9150-14
14.	Set Screw	9100-11	36.	Tieover Bracket	9160-TIE
15.	Fiber Washer	9100-20	37.	Nut	CM-50148
16.	Machine Pulley	9100-19	38.	Screw	9100-17
17.	Brush	TYX-3	39.	Lock Washer	9100-17A
18.	Cutter Shaft	9160-3	40.	Snap Ring	9100-21A
19.	Brush Nut	9100-25	41.	Switch	9160-SW
20.	Cutter Guard	9100-16	42.	Bottom Cover	9120-COVER
21.	Cap Screw	9100-17	43.	Screws 6-32 x 3/8"	22-48
22.	Washer	9100-17A	44.	DC Cable	DC-CABLE